

How to apply beaded wax

1. Set wax bath to 85°C
2. The glass bottle or jar should be around 20°C
3. Once the wax is melted, dip the glass bottle/jar in briefly at an angle of 60 degrees and spin one turn to remove excess wax.
4. Next, dip into cold water to provide a glossy finish.
5. Change the water often to keep it cool and clean.

1kg of beaded wax will seal approximately 265 bottles.

Please note the wax covering is for aesthetic appeal only and does not seal the product.

